



Dilapidation Survey Report

1 Sample Street, Melbourne VIC 3022

- √ 30+ Years' Experience In Reporting Services
- ✓ Our Quality Reports Make Roscon The Number #1 Choice
- \checkmark We conduct onsite audits including photos, not desktop audits
- ✓ ISO 9001 Accredited Systems & Procedures
- ✓ Member MBAV Platinum Master Builder (5630)
- √ Member Strata Community Australia
- √ Member Australian Institute of Project Management

Roscon Property Services

Roscon Property Services is the first property services provider to introduce central streamlined systems integrating property maintenance and quality controlled reporting services accredited by International Certifications, dedicated to support Owners Corporation managers.

Since 1987 we have evolved from our history of developing and constructing prestigious residential and high profile commercial/ industrial landmark projects. We have extended our service capabilities through our extensive construction, strata management and professional property services experience gained over 25 years, and filled the void between three property industries.

Built on solid foundations our clients rest assured in the comfort of knowing they're supported by Registered Building Practitioners, qualified professionals, fully insured and committed in protecting their responsibility to valued clients.

Mission Statement

"It is the policy of Roscon Property Services to deliver property Maintenance services to its clients in the most efficient and timely manner while respecting legal and statutory requirements. Roscon Property Services Pty Ltd operates under ISO 9001-2000 in the completion of its services. All staff & sub-contractors are expected to work according to our policies and procedures. The system employed by Roscon Property Services Pty Ltd is reviewed annually in order to ensure its consistency".

Instructed By

Name	XXX
Company	Owners Corporation
Address	XXX

Inspected & Compiled by

Inspector ID



10 February 2016

Dear XXX,

Thank you for using Roscon Property Services Pty Ltd for your Property Dilapidation Survey Report. I have attached a copy of the report that has been compiled by an experienced auditor.

Should you require further assistance or need clarification of anything that is contained within the report then please do not hesitate to contact us.

The attached report includes the following:

Part 1	Inspection Notes
Part 2	Introduction
Part 3	Detailed Dilapidation Survey Report – 1 Sample Street, Melbourne VIC 3022
Part 4	General Condition Photos – 1 Sample Street, Melbourne VIC 3022
Part 5	Terms and Conditions

The team at Roscon Property Services are available to assist you with any rectification concern that may eventuate and look forward to your call. Thank you for your continued business.

Yours Sincerely

Roscon Property Services Pty Ltd



Managing Director

AREI, RBP, CRE, Licensed Estate Agent

Registered Building Practitioner DB-U 13329, CB-U 4272

Member REIV, MBAV, SCA, NCTI

















Part 1: Inspection Notes

Roscon Property Services was commissioned by XXX of Owners Corporation to carry out a property dilapidation report at 1 Sample Street, Melbourne VIC 3022.

The purpose of the report is to record the condition of the property or areas surveyed at the time of the inspection and prior to construction works commencing adjacent to the property. This report is not a structural report; however it does include a photographic record of the main structural defects visible at the time of the survey. The report intendeds to contain an exhaustive list of minor defects that are found in nearly all buildings (general wear and tear, minor cracking, unevenness and blemishes). We have also reported on finishes to the building such as paint, ceiling, floor boards, window frames.

This report is not to be used for any other purpose. The report is for the exclusive use of the Owners Corporation of 1 Sample Street, Melbourne VIC 3022. No responsibility/liability is accepted as the result of the use of this report by any other party.

During the inspection we have not moved objects that could be covering defects in the structure. No testing has been carried out. Pit lids have not been lifted to inspect pit interiors. The buildings at the time of the inspection were fully furnished. There were wall and floor areas which were concealed by the furnishings, stored goods. Vegetation concealed some part of the property. The existence of asbestos products or other hazardous material has not been reported on.

Some photographs provided in this report are of general areas that may be affected by the proposed construction works and do not necessarily show defects. This report mainly records the existing conditions of the surrounding areas of the building adjoining the property where the construction works are taking place and also the existing conditions of the footpaths, street and nearby fences.

This report shall not be construed as a certificate of warranty of the building. The report does not cover issues such as building services, hazardous materials, fire safety, drainage, plant, machinery, illegal building works, nor does it consider requirements of the National Construction Code. Certification of any building or road works is excluded from this report.



















Part 2: Introduction

- 1. This report is intended to record the current condition of 1 Sample Street, Melbourne VIC 3022, prior to construction works commencing next door at 2 Sample St, the rear of which backs onto Sample Lane.
- 2. The site inspection was carried out on Monday 7th Feb 2016. The weather during the course of inspection was fine with clear skies for the most part of the day.
- 3. This report of condition contains the following definitions and their descriptions are as follows:
 - o Good No signs of wear of tear and able to perform the function for which it was installed.
 - o Fair Showing signs of wear/soiling but still serviceable and functioning adequately.
 - o **Poor** Subject to hard and long term wear with repair and/or renovation generally necessary.
- 4. The below tables identify the classification of cracks and their sizes in relation to building elements.
- a) Classification of Identified Defects with Reference to Walls

Impact Category	Description of typical defect to walls	Approximate crack width limit
0	Hairline cracks	< 0.1 mm
1	Fine cracks which do not need repair	0.1 mm to 1.0 mm
2	Cracks noticeable but easily filled. Doors and windows stick slightly.	1 mm to 5 mm
3	Cracks can be repaired and possibly a small amount of wall will need to be replaced. Doors and windows stick. Service pipes can fracture. Weather-tightness often impaired	5 mm to 15 mm, or a number of cracks 3 mm to 5 mm in one group
4	Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Window or door frames distort. Walls lean or bulge noticeably. Some loss of bearing in beams. Service pipes disrupted.	15 mm to 25 mm but also depends on number of cracks
5	As above but worse, and requiring partial or complete rebuilding. Roof and floor beams lose bearing and need shoring up. Windows broken with distortion. If compressive damage, severe buckling and bulging of the roof and walls.	> 25 mm

















b) Classification of Damage to Concrete Floors

Impact Category	Description of typical damage	Approximate crack width limit in floor	Change of offset from 3m straight placed over defect
0	Hairline crack, insignificant movement of slab from level	< 0.3 mm	< 8mm
1	Fine but noticeable cracks. Slab reasonably level	< 1.0 mm	<10mm
2	Distinct cracks, Slab noticeable curved or change in level	< 2.0 mm	<15mm
3	Wide cracks. Obvious curvature or change in level	2mm – 4mm	15mm – 25mm
4	Gaps in slab. Disturbing curvature or change in level	4mm – 10mm	> 25 mm

















Part 3: Detailed Dilapidation Survey Report

1 Sample Street, Melbourne VIC 3022

Item	Photographic Evidence	Assessments	
1.	WARNING 24 HOUR MONITORED VIDEO SECURITY WHENTY La	Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Minor imperfections on wall of building at entrance of Sample Wall is dirty and contains minor cracks Discolouration is also visible 	e 1 Lane.	
2.		Assessment Type: Good Fair Poor	
		1	
Location: Sample 1 Lane	 Auditors Comments: Differences in level on asphalt ground to entrance on laneway Discolouration is evident on asphalt ground Indentations and staining is clearly visible 	У	

















Item	Photographic Evidence	Assessments	
3.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: General condition of Sample 1 Lane, dirty Asphalt discoloured Stains evident on ground Kerb is in cracking and showing signs of wear and tear 		
4.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: General condition of Sample 1 Lane, dirty Asphalt discoloured Stains evident on ground Kerb is in cracking and showing signs of wear and tear 		

















Item	Photographic Evidence	Assessments	5
5.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Asphalt ground is uneven and discoloured Kerb is cracking and contains indentations Windows all along Sample 1 Lane are dirty and dusty 		
6.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Asphalt ground is uneven and discoloured Kerb is cracking and contains indentations Windows all along Sample 1 Lane are dirty and dusty 		

















Item	Photographic Evidence	Assessments	
7.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Asphalt ground is uneven and discoloured Kerb is cracking and contains indentations Windows all along Sample 1 Lane are dirty and dusty 		
8.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Walls are generally dirty and paint is peeling off in certain are Windows along Sample 1 Lane are dusty and dirty 	eas	

















Item	Photographic Evidence	Assessments	
9.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Patchwork is evident on asphalt lane way Kerb is cracking and is discoloured. Mortar on in kerb joints is dirty and rough Walls are generally dirty and dusty 		
10.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Eastern Elevation	 Auditors Comments: Kerb is cracking and is discoloured. Mortar on in kerb joints is dirty and rough Walls are generally dirty and dusty 	,	

















Item	Photographic Evidence	Assessments	
11.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	Auditors Comments: ● General view of Sample 1 Lane		
12.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Patchwork is evident on asphalt lane way Kerb is cracking and is discoloured. Mortar on in kerb joints is dirty and rough Walls are generally dirty and dusty 		

















Item	Photographic Evidence	Assessments	2
13.		Assessment Type: Good Fair Poor	
Location	Auditors Comments:	1 2 3 4 5	
Location: Sample 1 Lane	 Patchwork is evident on asphalt lane way Kerb is cracking and is discoloured. Mortar on in kerb joints is dirty and rough Walls are generally dirty and dusty 		
14.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Patchwork is evident on asphalt lane way Kerb is cracking and is discoloured. Mortar on in kerb joints is dirty and rough Walls are generally dirty and dusty 		

















Item	Photographic Evidence	Assessments	
15.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane Lane	Auditors Comments: General view of Sample 1 Lane. Laneway shows signs of minor cracking and is discoloured and	d uneven	
16.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Sample 1 Lane	General view of Sample 1 Lane. Laneway shows signs of minor cracking and is discoloured and	d uneven	

















Item	Photographic Evidence	Assessments
17.		Assessment Type: Good Fair Poor
Location:	Auditors Comments:	1
Sample 1 Lane	 Windows along Sample 1 Lane are quite dirty and dusty Walls are also generally dirty and show signs of dust residue 	
18.		Assessment Type: Good Fair Poor
		1
Location: Sample 1 Lane	Windows along Sample 1 Lane are quite dirty and dusty Walls are also generally dirty and show signs of dust residue	

















Item	Photographic Evidence	Assessments	}
19.		Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	Auditors Comments: Windows along Sample 1 Lane are quite dirty and dusty Walls are also generally dirty and show signs of dust residue		
20.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Concrete kerb is discoloured and shows signs of cracking Wall near roller door is chipped on the corner Aggregate is showing through concrete driveway 	g	

















Item	Photographic Evidence	Assessments	3
21.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Concrete kerb is discoloured and shows signs of cracking Wall near roller door is chipped on the corner Aggregate is showing through concrete driveway 	g	
22.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	Auditors Comments: ● General view of Sample 1 Lane		

















Item	Photographic Evidence	Assessments	;
23.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Concrete kerb is discoloured and shows signs of crackin Wall near roller door is chipped on the corner Roller door is dirty and discoloured 	g	
24.		Assessment Type: Good Fair Poor	
	500	Impact Category: 1 2 3 4 5	
Location: Sample 1 Lane	 Auditors Comments: Wall is dirty with minor indentations visible on the surface Stains are also visible underneath the no standing sign 		

















Item	Photographic Evidence	Assessments	}
27.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample Lane	 Auditors Comments: Kerb shows major signs of wear and tear with large indentation Asphalt laneway is discoloured and uneven Stains are evident on wall near bins 	ons and cracks	
28.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: North Elevation	 Auditors Comments: Small indentations are visible at the base of the column to the Footpath is dirty and discoloured and there are minor cracks Cracks are also evident to the column and rendered wall junc 	in the concrete.	<i>5</i> .

















Item	Photographic Evidence	Assessments
29.		Assessment Type: Good Fair Poor
Location: Sample Lane	Auditors Comments: • General view of Sample Lane	2 3 4 5
30.		Assessment Type: Good Fair Poor
		1
Location: Corner of Sample Lane & Sample 1 Lane	Auditors Comments: General view of Sample/Sample 1 Lane	· —

















Item	Photographic Evidence	Assessments
31.		Assessment Type: Good Fair Poor
		1
Location: Sample Lane	View of rear Sample lane	
32.		Assessment Type: Good Fair Poor
		1
Location: Sample Lane	 Auditors Comments: Concrete kerb is dirty, cracking and dents are visible on the se Asphalt lane is discoloured and uneven Driveway is uneven and cracking 	urface

















Item	Photographic Evidence	Assessments	
33.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Rear Sample Lane	■ General view of rear of Sample Lane		
34.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Corner Sample & Sample 1 Lane	 Auditors Comments: Asphalt laneway is discoloured, uneven and shows signs of m Kerb is dirty and uneven 	inor cracking	

















Item	Photographic Evidence	Assessments	5
35.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample Lane	 Auditors Comments: Concrete kerb is dirty, cracking and dents are visible on the sum of the	urface	
36.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Rear Sample Lane	 Auditors Comments: Concrete kerb is dirty, cracking and dents are visible on the sum of the sum	urface	

















Item	Photographic Evidence	Assessments	
37.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample Lane	 Auditors Comments: Concrete kerb is dirty, cracking and dents are visible on the si Asphalt lane is discoloured and uneven Driveway is uneven and cracking 	urface	
38.	N SWOOD PRINT REAL PRINTS AND	Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Rear Sample Lane	 Auditors Comments: Doors leading into building are dirty Concrete floor in front of doors is dirty, cracking and uneven Corners of building show signs of minor cracking 		

















Item	Photographic Evidence	Assessments	5
39.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Sample Laneway	 Auditors Comments: Concrete kerb is dirty, cracking and dents are visible on the set Asphalt lane is discoloured and uneven Driveway is uneven and cracking Stop sign is laying on the ground 	urface	
40.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample Lane	Auditors Comments: General view of Sample Lane	,	

















Item	Photographic Evidence	Assessments	
41.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Sample Lane	 Auditors Comments: Concrete kerb is dirty, cracking and dents are visible on the sum of the	urface	
42.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample Lane Rear Driveway	Auditors Comments: Concrete driveway contains black stains and also shows signs	of minor cracking	

















Item	Photographic Evidence	Assessments	5
43.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample Laneway – rear Driveway	General view of rear driveway		
44.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: West Elevation & Driveway	 Auditors Comments: Corner guards to edge of building are scratched and dirty Concrete driveway is stained and shows signs of cracking Concrete kerb is dirty, cracking and dents are visible on the sum Asphalt lane is discoloured and uneven 	urface	

















Item	Photographic Evidence	Assessments	5
45.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location:	Auditors Comments:		
Sample Lane – rear	Corner guards to edge of building are scratched and dirty		
Driveway	Concrete driveway is stained and shows signs of cracking		
46.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location:	Auditors Comments:		
Sample Lane	 Window frames are dirty and discoloured Windows are generally dirty along Sample Lane Walls are stained and show signs of minor cracking 		

















Item	Photographic Evidence	Assessments	3
47.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Corner Sample and private laneway	 Auditors Comments: Windows and frames are generally dirty with scuff marks Wall to Sample lane is also generally dirty with stains and ma 	rks evident throughout	
48.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Corner Sample and private laneway	 Auditors Comments: Kerb is cracked, chipped and uneven Walls are dirty and stained 		

















Item	Photographic Evidence	Assessments	S
49.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private Laneway	 Auditors Comments: Private laneway asphalt ground is cracking in certain areas Large indentations and chips are evident throughout Ground is generally dirty and stained 		
50.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Concrete is cracking on either side of the drainage grate. Aggregate is exposed confirming normal wear and tear and states. 	tains are evident through	out.

















Item	Photographic Evidence	Assessments	5
51.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
<u>Location:</u> Private	Auditors Comments:		
laneway	 Private laneway asphalt ground is cracking in certain areas Large indentations and chips are evident throughout Ground is generally dirty and stained Concrete footpath has exposed aggregate and very dirty 		
52.		Assessment Type: Good Fair Poor	
		Impact Category:	
		1 2 3 4 5	
Location:	Auditors Comments:		
Private laneway	General view of private laneway		

















Item	Photographic Evidence	Assessments
53.		Assessment Type: Good Fair Poor
		Impact Category:
Location: Private laneway	 Auditors Comments: General view of private laneway Concrete path has aggregate exposed, is uneven and dirty the Asphalt laneway contains stains and shows signs of normal w 	
54.		Assessment Type: Good Fair Poor
		1
Location: Private laneway	Auditors Comments: Close up of private laneway containing large indentation and	cracking

















Item	Photographic Evidence	Assessments	S
55.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible.	dirty, stained and has agg	gregate
56.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible.	dirty, stained and has agg	gregate

















Item	Photographic Evidence	Assessments	5
57.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Private Laneway	 Auditors Comments: General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible. 	dirty, stained and has agg	gregate
58.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private Laneway	 Auditors Comments: General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible. Walls along laneway are also dirty and stained 	dirty, stained and has agg	gregate

















Item	Photographic Evidence	Assessments	
59.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Windows are dirty and dusty 	ns to the surface.	
60.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample Lane	 Auditors Comments: General view of Sample lane. Kerb is chipped and shows signs of wear and tear 		

















Item	Photographic Evidence	Assessments	
61.		Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5	
Location: Private Laneway	 Auditors Comments: General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible. 	dirty, stained and has aggr	egate
62.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Private Laneway	General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible.	dirty, stained and has aggr	egate

















Item	Photographic Evidence	Assessments	3
63.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private Laneway	 Auditors Comments: General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible. 	dirty, stained and has agg	regate
64.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Private Laneway	Asphalt ground in laneway shows signs of wear and tear with evident throughout	minor indentations and s	stains

















Item	Photographic Evidence	Assessment	S
65.	ADDITION OF SERVICE OR AVAILABLE THE OWNERS OF A	Assessment Type:	
		Good	
		Fair	
		Poor	
		Impact Category:	
		1 2 3 4 5	
Location:	Auditors Comments:		
Private			
laneway	 General condition of asphalt in private laneway is dirty, stains certain areas. Minor cracking and normal wear and tear is also visible. Kerb is chipped and uneven 	ed and nas aggregate exp	oosed in
66.		Assessment Type:	
		Good	
		Fair	
		Poor	
		Impact Category:	
		1	
		2	
		3	
		4	
		5	
Location:	Auditors Comments:		
Private	Conoral condition of conholt in private leaves to district	ad and is showing!	f mir = =
laneway	 General condition of asphalt in private laneway is dirty, stains cracking throughout 	ea and is snowing signs o	T minor
	Minor cracking and normal wear and tear is also visible.		
	Kerb is chipped and uneven		

















Item	Photographic Evidence	Assessments	S
67.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible.	dirty, stained and has agg	gregate
68.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	General condition of concrete footpath in private laneway is exposed in certain areas. Minor cracking and normal wear and tear is also visible.	dirty, stained and has agg	gregate

















Item	Photographic Evidence	Assessments
69.		Assessment Type: Good Fair Poor
		1
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Windows are dirty and dusty 	ns to the surface.
70.		Assessment Type: Good Fair Poor
		1
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Windows are dirty and dusty Window frames are also dirty and have minor scuff marks on 	

















Item	Photographic Evidence	Assessments	
71.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfection Windows are dirty and dusty Window frames are also dirty and have minor scuff marks on Concrete path is dirty and contains minor stains 		
72.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private Laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Windows are dirty and dusty Window frames are also dirty and have minor scuff marks on Concrete path is dirty and contains minor stains 		

















Item	Photographic Evidence	Assessments	S
73.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfection Windows are dirty and dusty Window frames are also dirty and have minor scuff marks on Concrete path is dirty and contains minor stains 		
74.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	Auditors Comments: General view of private laneway		

















Item	Photographic Evidence	Assessments
75.		Assessment Type: Good Fair Poor
		1
Location: Private laneway	 Auditors Comments: Asphalt is dirty and showing signs of minor cracking throughout the concrete path is dirty and contains minor stains 	put
76.		Assessment Type: Good Fair Poor
		1
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips thro 	

















Item	Photographic Evidence	Assessments
77.		Assessment Type: Good Fair Poor
		Impact Category:
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips thro 	
78.	DANGER VEEP OUT CET POINT NEED TO SEE	Assessment Type: Good Fair Poor
		1
Location: Private laneway	Auditors Comments: Close up of substation doors in private laneway	

















Item	Photographic Evidence	Assessment	S
79.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	Concrete path is showing signs of normal wear and tear with Kerb is chipped in certain areas and also dirty and discoloured Concrete pit lids are stained and contain minor cracks		louration
80.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Concrete path is showing signs of normal wear and tear with Kerb is chipped in certain areas and also dirty and discoloured Concrete pit lids are stained and contain minor cracks 		louration

















Item	Photographic Evidence	Assessments	
81.		Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Concrete path is showing signs of normal wear and tear with Kerb is chipped in certain areas and also dirty and discoloured Concrete pit lids are stained and contain minor cracks 		ouration
82.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Concrete path is showing signs of normal wear and tear with Kerb is chipped in certain areas and also dirty and discoloured Concrete pit lids are stained and contain minor cracks 		ouration

















Item	Photographic Evidence	Assessments	
83.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips thro 		
84.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips thro 		

















Item	Photographic Evidence	Assessments
85.		Assessment Type: Good Fair Poor
		1
Location: Private laneway	Wall along private laneway contains some minor imperfection Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips through	
86.		Assessment Type: Good Fair Poor
	WARNING	1
Location: Private laneway	Small indentation evident on private laneway wall	<u>, </u>

















Item	Photographic Evidence	Assessments
87.		Assessment Type: Good Fair Poor
		Impact Category: 1 2 3 4 5
Location: Private Ianeway	 Auditors Comments: Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips thro 	pughout
88.		Assessment Type: Good Fair Poor
		1
Location: Private laneway	Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips through	bughout

















Item	Photographic Evidence	Assessments	
89.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Private lane	Auditors Comments: General view of private laneway asphalt		
90.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Private laneway	 Auditors Comments: Wall along private laneway contains some minor imperfectio Concrete path is dirty and contains minor stains Concrete kerb has aggregate exposed and contains chips thro 		

















Item	Photographic Evidence	Assessments
91.		Assessment Type: Good Fair Poor Impact Category:
Location: Sample Lane	Auditors Comments: • General view of Sample lane	3 4 5
92.		Assessment Type: Good Fair Poor
		1
Location: Sample Lane	Auditors Comments: • General view of Sample lane	

















Item	Photographic Evidence	Assessments
93.		Assessment Type: Good Fair Poor
		1
Location: Sample Lane	 Auditors Comments: General view of Private laneway from Sample lane corner 	
94.		Assessment Type: Good Fair Poor
		1
Location: Sample/Sample 1 Lane	Auditors Comments: General view of intersection of Sample/Sample 1 Lane	

















Item	Photographic Evidence	Assessments	3
95.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample	Auditors Comments:		
St	General view of front façade on Sample Street		
96.	0-503	Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample St	Auditors Comments: • General view of front entrance from Sample	1	

















Item	Photographic Evidence	Assessments	5
97.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
<u>Location:</u> Sample	Auditors Comments:		
St	Cracks are visible on the front façade		
98.	Part of the ground marble panel has a giant chip piece miss	Assessment Type: Good Fair Poor	
		1 2 3 4 5	
<u>Location:</u> Sample	Auditors Comments:		
St	Multiple indentations on cement wall		

















Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5 100. Assessment Type: Good Fair Poor Impact Category:	Item	Photographic Evidence	Assessments	
Location: Sample St Ocorner part of cement wall has been damaged and has pieces missing from it Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5 1 1 2 3 4 5 1 1 2 3 4 4 5 1 1 2 3 4 4 5 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 1 1 1 2 3 4 4 5 5 1 1 1 2 3 4 4 5 5 1 1 1 2 3 4 4 5 5 1 1 1 2 3 4 4 5 5 1 1 1 2 3 4 4 5 5 1 1 1 2 3 4 4 5 5 1 1 1 2 3 3 4 4 5 5 1 1 1 1 2 3 3 4 4 5 5 1 1 1 1 1 1 2 1 3 3 4 4 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	99.		Good Fair	
Sample St Corner part of cement wall has been damaged and has pieces missing from it Assessment Type: Good Fair Poor Matter Category: Impact Category:			1 2 3 4	
St Corner part of cement wall has been damaged and has pieces missing from it Assessment Type: Good Fair Poor Mark Mark		Auditors Comments:	<u> </u>	
Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5 Location: Entry Stairs Assessment Type: Good Fair Poor Assessment Type: Assessment Type: Assessment Type: Auditors Comments:		Corner part of coment wall has been damaged and has piece	es missing from it	
Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5 Location: Entry Stairs Auditors Comments:		5 Corner part or certificity was rias been damaged and has piece	es missing nom te	
Fair Poor Impact Category: 1 2 3 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	100.		Assessment Type:	
Poor Impact Category: 1 2 3 4 5 Location: Entry Stairs Auditors Comments:				
Location: Entry Stairs Auditors Comments:				
Location: Entry Stairs Auditors Comments:			Impact Category:	
Location: Entry Stairs Auditors Comments:				
Location: Entry Stairs Auditors Comments:				
Location: Entry Stairs Auditors Comments:				
Location: Auditors Comments: Entry Stairs				
Entry Stairs			5	
		Auditors Comments:		
	Lifti y Stalls	4 th stair shows multiple cracks on the tiles		

















Item	Photographic Evidence	Assessments	5
101.		Assessment Type: Good Fair Poor	
Location		Impact Category: 1 2 3 4 5	
Location: Entry Stairs	 Auditors Comments: Multiple chips present on the tiles on the stairs 		
102.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Entry Stairs	 Auditors Comments: Damaged tiles and metal sticking out from cement floor 		

















Item	Photographic Evidence	Assessments	5
103.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Entry Stairs	Auditors Comments: • Damage to one of the tiles		
104.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Entry Stairs	Damage to one of the tiles		

















Item	Photographic Evidence	Assessments	5
105.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Front Door - Ceiling	 Auditors Comments: Cracks a visible on the ceiling to the front door 		
106.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Front Door	Auditors Comments:		
FIGHT DOOF	General view of entry to complex		

















Item	Photographic Evidence	Assessments	i
107.		Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5	
Location: Front Door	Auditors Comments:		
	General view of entry to complex		
108.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Front Door	Auditors Comments:Long crack on floor marble		

















Item	Photographic Evidence	Assessments	S
109.		Assessment Type: Good Fair Poor Impact Category: 2 3 4 5	
Location: Front Door	Auditors Comments: • Large crack on floor tiles near front entry		
110.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Front Door	Auditors Comments: Crack on floor tiles near front entry		

















Item	Photographic Evidence	Assessments	5
111.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Front Door	Auditors Comments:Part of the floor tile has been chipped		
112.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Lobby	Auditors Comments: General view of lobby		

















113. **Assessment Type:** Good Fair Poor **Impact Category: Location: Auditors Comments:** Lobby General view of lobby 114. **Assessment Type:** Good Fair **Poor Impact Category:** 1 2 3 **Location: Auditors Comments:** Lobby Crack in the ceiling near the column closest to the front door

















Item	Photographic Evidence	Assessments	S
115.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Lobby	Small crack above elevators		
116.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Lobby	Small crack on the column closest to the elevators		

















Item	Photographic Evidence	Assessments	5
117.		Assessment Type: Good Fair Poor	
		Impact Category: 2 3 4 5	
<u>Location:</u> Hallway	 Auditors Comments: General view of ground floor apartments hallway 		
118.	- O	Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Hallway	Auditors Comments:	,	
	General view of apartment G02		

















Item	Photographic Evidence	Assessments	
119.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Hallway	 Auditors Comments: Minor crack between skirting board and ceiling on the entra 	ance to the hallway	
120.		Assessment Type: Good Fair Poor	
	500	1 2 3 4 5	
Location: Hallway	Auditors Comments: Crack in ceiling near apartment G02		

















Item	Photographic Evidence	Assessments	;
121.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Lobby	Small crack on floor tiles near the entrance to the hallway		
122.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
Location: Lobby	Auditors Comments:		




































Item	Photographic Evidence	Assessments	}
125.		Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5	
Location: Lobby	Auditors Comments: • Long crack next to the column closest to the elevators		
126.		Assessment Type: Good Fair Poor	
		1 2 3 4 5	
<u>Location:</u> Lobby	 Auditors Comments: Crack on the western side of the building near the couch 		

















Item	Photographic Evidence	Assessments	5
127.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Hallway	Auditors Comments:Gap in skirting board near apartment G02		
128.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Front Door	Auditors Comments: Crack in cornice strip in the front door area near the ceiling		



































Item	Photographic Evidence	Assessments	S
131.		Good Fair Poor Impact Category: 2 3 4 5	
Location: Sample	Auditors Comments:		
St	Part of the ceiling near the entrance sign is damaged		
132.		Assessment Type: Good Fair Poor	
	5.503	Impact Category: 1 2 3 4 5	
Location: Sample St	Auditors Comments: • Concrete splatter near numbering of building	1	

















Item	Photographic Evidence	Assessments	;
133.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample St	 Auditors Comments: Crack present on facade Rusting present on metal supports 		
134.		Assessment Type: Good Fair Poor	
		Impact Category: 1 2 3 4 5	
Location: Sample St	Auditors Comments: Crack present under metal grill.	,	

















Item	Photographic Evidence	Assessments	5
135.		Assessment Type: Good Fair Poor Impact Category: 1 2 3 4 5	
Location: Sample St	Auditors Comments: • Crack on front façade on left side of front entrance	Assessment Type: Good Fair Poor	
	HOUSE WAR	Impact Category: 1 2 3 4 5	
Location: Sample St	Multiple cracks front façade above front entrance		

















Part 4: General Condition Photos





























Part 5: Terms and Conditions

The following information is very important and forms an integral part of this report.

Before you decide to purchase this property you should read and understand the following important information. It will help explain what is involved in a Standard Property Inspection, the difficulties faced by an inspector and why it is not possible to guarantee that a property is free of defects, latent or otherwise. This information forms an integral part of the report. The general adequacy of site drainage is not included in the Standard Property Inspection Report. Comments on surface water drainage are limited as where there has been either little or no rainfall for a period of time, surface water drainage may appear to be adequate but then during periods of heavy rain, may be found to be inadequate. Any comments made in this section are relevant only in light of the conditions present at the time of inspection. It is recommended that a Smoke Test be obtained to determine any illegal connections, blocked or broken drains.

This is a Visual Inspection only and in Accordance with AS4349.1

This visual inspection is limited to those areas and sections of the property fully accessible and visible to the Inspector at the time and on the date of Inspection. The inspection DID NOT include breaking apart, dismantling, removing or moving objects including, but not limited to, foliage, mouldings, roof insulation/sarking membrane, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The Inspector CANNOT see inside walls, between floors, inside skillion roofing, inside the eaves, behind stored goods in cupboards, or other areas that are concealed or obstructed. The inspector DID NOT dig, gouge, force or perform any invasive procedures. In an occupied property it must be understood that furnishings or household items may conceal defects which may only be revealed when the items are removed. No detailed inspection is inferred to external areas over 3.6 metres above the natural ground level.

Scope of Report

The Standard Property Report is not intended as a certificate of compliance of the property within the requirements of any Act, regulation, ordinance or by-law, or, as a warranty or an insurance policy against problems developing with the building in the future.

Limitations

Nothing contained in the Report implies that any inaccessible or partly inaccessible area(s) or section(s) of the property being inspected by the Inspector on the date of the inspection were free from defects latent or otherwise.

No responsibility can be accepted for defects which are latent or otherwise not reasonably detected on a visual inspection without interference with or removal of any of the structure including fixtures or fittings within the building.

This Standard Property Report does not contain any assessment or opinion in relation to any item, which is the subject of a Special Purpose Property Report (as defined in AS4349.1), or any matter where the inspection or assessment of which is solely regulated by Statute. Special Purpose Property Reports include comment on the following: Common property areas, environmental concerns such as sunlight, privacy, streetscape and views. Proximity of property to flight paths, railways and busy traffic or other neighbourhood issues. Noise levels, health and safety issues including the presence of asbestos or lead. Heritage concerns. Security or fire protection. Analysis of site drainage apart from surface water drainage. Swimming pools and spas. Detection and identification of illegal and unauthorised building and plumbing work. Durability of exposed finishes.

This report does not constitute a building survey, and is only intended to record the current condition of the building fabric and exposed finishes. In preparation of this report no tests have been carried out on any service installations such as heating, alarm systems, emergency lighting, and smoke or heat detectors. Where the terms 'left hand' and 'right hand' are used, it is assumed that the observer is facing the element being described. We advise that we have not inspected parts of the building built-in, covered up or otherwise made inaccessible, and therefore cannot comment as to whether they are free from defect or infestation. We also advise that we have not tested services or carried out tests for any deleterious materials. We have not commented on any environmental issues, hazardous materials and the like and did not form part of the brief.

















Important Information

Any person who relies upon the contents of this Report does so acknowledging that the above clauses, definitions and disclaimers that follow define the Scope and Limitations of the inspection and form an integral part of the report.

Disclaimer of Liability

No liability shall be accepted on account of failure of the Report to notify any problems in any area(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for Inspection is denied by or to the Inspector (including but not limited to any area(s) or section(s) so specified by the Report.

Disclaimer of Liability to Third Parties

This report is made solely for the use and benefit of the Client named on the front of this report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part does so at their own risk.

Report Definition

This report is limited to a visual inspection of areas where reasonable access is available at the time of inspection. It does not purport to be geological as to foundation integrity or soil conditions, engineering as to structural, nor does it cover the condition of electrical, plumbing, gas or motorised appliances. It is strongly recommended that an appropriately qualified contractor check these services prior to purchase.

As the date if this report we have identified the items as listed herein, we do not accept any responsibility for items which may be damaged after the inspection has been completed.

As a matter of course, and in the interests of safety, all prospective purchasers should have an electrical report carried out by a suitably qualified contractor. This report is limited to (unless otherwise noted) the main structure on the site and any other building, structure or outbuilding specifically named within the report.

This Report attempts to assist in judging a building according to its age and level of maintenance and in providing relative comparisons. This inspection and report is not to be considered all encompassing dealing with a building from every aspect. Rather it should be seen as a reasonable attempt to identify any significant defects visible at the time of the inspection. It is unrealistic to expect comment on minor defects or imperfections in the Standard Property Report. If this is required, a Special Purpose Property Report is recommended.

Whilst buildings may have many pleasing features there are few without defects and many are due naturally to age deterioration. Subject to the level of maintenance on the building it is common for the number of faults to have increased with age.

All items that are considered to be concealed or latent defects are excluded.

Shower Recesses: Tests may be made on shower recesses to detect leaks (if water is connected). The tests may not reveal leaks or show incorrect waterproofing if silicone liquid or masonry sealant has been applied prior to the inspection. Such application is a temporary waterproofing measure and may last for some months before breaking down. The tests on shower recesses are limited to running water within the recesses and visually checking for leaks. As showers are only checked for a short period of time, prolonged use may reveal leaks that were not detected at the time of inspection. If there is no evidence of a current leak during inspection that does not necessarily mean that the shower does not leak.

Glass Caution: Glazing in older houses (built before 1978) may not necessarily comply with current glass safety standards AS1288. In the interests of safety, glass panes in doors and windows especially in trafficable areas should be replaced with safety glass or have shatterproof film installed unless they already comply with the current standard.

Stairs & Balustrades: Specifications have been laid down by the Australian Building Code - Section 3.9 covering stairs, landings and balustrades to ensure the safety of all occupants and visitors in a building. Many balustrades and stairs built before 1996 may not comply with the current standard. You must upgrade all such items to the current standard to improvafety.

















Swimming Pools: If a swimming pool is present it should be the subject of a Special Purpose Property Report. A detailed inspection on the status or serviceability of any swimming pool or associated pool equipment has not been carried out and is not within the scope of this report. Additionally, to adequately inspect a swimming pool, the water must be completely drained and all internal surfaces must be fully accessible.

This report may contain notable observations, together with what is considered to be helpful information and advice.

This report does not identify timber-destroying pests. A timber pest inspection report should be obtained from a qualified timber pest inspector.

If any cost of work estimates is given, these are merely opinions and should be taken as a general guide only. In the building industry, experience has shown that prices vary considerably and you must obtain independent quotations on any significant notable item from several contractors prior to purchase.

The operation of fireplaces, chimneys, alarm systems, intercom systems, electrical and mechanical appliances, air conditioning systems, smoke detectors and residual current devices have not been tested and are the subject of a Special Purpose Property Report. Should you require an inspection to be carried out on any item not specifically covered by this report, please request a Special Purpose Property Report on the specific item required.

No report is made on the presence, operation, installation or cabling of any free to air or pay television system.

Lighting Installations

It should be noted that this inspection was done during daylight hours and therefore the adequacy of lighting in darkness could not be directly assessed.

Electrical Installations

We have carried out a thorough visual inspection of the common property and assets visible from the common property areas. If there were any visible electrical installation issues they have been included in this section of the report. We have not carried out a thorough inspection of electrical installation and the main switchboard, as we are not qualified to do so, please ensure that a suitably qualified electrical contractor carries out a thorough visual inspection at least every 2 years, this inspection can be incorporated with the testing of the Residual Current Device if Community Circuits are present.

Plumbing, Gutters & Downpipes and Roofs

We have carried out a thorough visual inspection of the common property and assets visible from the common property areas. If there were any visible plumbing, gutters and downpipes or roof issues they have been included in this section of the report. We have not carried out a thorough inspection of the plumbing, gutters and downpipes and roof, as we are not qualified to do so, please ensure that a suitably qualified plumbing contractor (who is qualified to undertake roof inspections) carries out a thorough regular inspection. We will recommend a qualified plumber to inspect if an issue is found.

Glass

This report only addresses glass requiring obvious replacement. It does not cover the Building Code, Australian Standard and safety requirements of glass installed in the common property.

Balcony Balustrades

Wherever balcony balustrades are installed, please be advised that a comprehensive inspection of balcony railings was not carried out as part of this report. Also this report is only a visual inspection of areas accessible from the common property; therefore all balcony balustrades are not viewed. If there are any visible signs of corrosion on the balustrade including fixings and/or if the balustrades are over 10 years old a detailed inspection and testing of balustrades should be undertaken.

















Pest Reports

If there are any visible signs of termite damage it is included in this report. We have not carried out a pest inspection of the site; as we are not qualified to do so, please ensure that a suitably qualified pest inspection contractor carries out thorough regular inspections.

Services

Important Notes: In regard to plumbing or electrical, it should be noted that we are not plumbers or electricians and any comment made is not that of a qualified plumber or electrician. We recommend that a qualified contractor be engaged to make comment.



Roscon Property Services

Offices 150 Sydney Road Coburg VIC 3058 | Level 50, 120 Collins Street Melbourne VIC 3000 Tel 1800 767 266 | Email info@roscon.com Web roscon.com.au















